

**CLASS VI INJECTION WELL:  
QUALITY ASSURANCE AND SURVEILLANCE PLAN  
40 CFR 146.90 (k)**

Plan Revision Date:

**July 2023**

Prepared for:

**River Parish Sequestration – RPN 4**

**Iberville Parish, Louisiana**

## Table of Contents

<b>Title and Approval Sheet.....</b>	<b>vii</b>
<b>Distribution List.....</b>	<b>viii</b>
<b>List of Acronyms/Abbreviations.....</b>	<b>ix</b>
<b>A. Project Management.....</b>	<b>1</b>
<b>A.1 Project/Task Organization.....</b>	<b>1</b>
A.1.a Key Individuals and Responsibilities.....	1
A.1.b Independence from Project Quality Assurance Manager and Data Gathering .....	1
A.1.c QA Project Plan Responsibility .....	1
A.1.d Organizational Chart for Key Project Personnel.....	2
<b>A.2 Problem Definition/Background.....</b>	<b>2</b>
A.2.a Reasoning .....	2
A.2.b Reasons for Initiating the Project.....	3
A.2.c Regulatory Information, Applicable Criteria, Action Limits.....	3
<b>A.3 Project/Task Description. ....</b>	<b>4</b>
A.3.a Summary of Work to be Performed.....	4
A.3.b Geographic Locations.....	11
A.3.c Resource and Time Constraints .....	11
<b>A.4 Quality Objectives and Criteria.....</b>	<b>11</b>
A.4.a Performance/Masurement Criteria .....	11
A.4.b Precision.....	20
A.4.c Bias .....	20
A.4.d Representativeness .....	20
A.4.e Completeness .....	21
A.4.f Comparability.....	21
A.4.g Method Sensitivity .....	21
<b>A.5 Special Training/Certifications .....</b>	<b>22</b>
A.5.a Specialized Training and Certifications.....	22
A.5.b Training Provider and Responsibility.....	23
<b>A.6 Documentation and Records.....</b>	<b>23</b>
A.6.a Report Format and Package Information .....	24
A.6.b Other Project Documents, Records, and Electronic Files .....	24
A.6.c Data Storage and Duration .....	24
A.6.d QASP Distribution Responsibility .....	24

<b>B. Direct Data Generation and Acquisition.....</b>	<b>24</b>
<b>B.1 Sampling Process Design.....</b>	<b>24</b>
B.1.a Design Strategy .....	25
Groundwater Monitoring Strategy .....	25
CO <sub>2</sub> Stream Monitoring Strategy .....	26
Corrosion Monitoring Strategy .....	26
Surface and Near-Surface Monitoring Strategy .....	27
B.1.b Sampling Site Contingency.....	27
B.1.c Critical/Informational Data.....	28
B.1.d Sources of Variability .....	28
<b>B.2 Sampling Methods.....</b>	<b>29</b>
B.2.a Sampling SOPs.....	29
B.2.b In situ Monitoring.....	31
B.2.c Continuous Monitoring .....	31
B.2.d Sample Homogenization, Composition, Filtration .....	31
B.2.e Sample Containers and Volumes.....	31
B.2.f Sample Preservation .....	32
B.2.g Cleaning/Decontamination of Sampling Equipment .....	32
B.2.h Support Facilities .....	33
B.2.h Corrective Action, Personnel, and Documentation .....	33
<b>B.3 Sample Handling and Custody .....</b>	<b>34</b>
B.3.a Maximum Hold Time/Time Before Retrieval.....	34
B.3.b Sample Transportation .....	35
B.3.c Sampling Documentation.....	35
B.3.d Sample Identification .....	35
B.3.e. Sample Chain-of-Custody.....	35
<b>B.4 Analytical Methods .....</b>	<b>35</b>
B.4.a Analytical SOPs.....	35
B.4.b Equipment/Instrumentation Needed .....	36
B.4.c Method Performance Criteria.....	36
B.4.d Analytical Failure .....	36
B.4.e Sample Disposal .....	36
B.4.f Laboratory Turnaround.....	36
B.4.g Method Validation for Nonstandard Methods .....	36
<b>B.5 Quality Control .....</b>	<b>36</b>
B.5.a QC activities .....	36
B.5.b Exceeding Control Limits.....	37
B.5.c Calculating Applicable QC Statistics .....	37

<b>B.6 Instrument/Equipment Testing, Inspection, and Maintenance .....</b>	<b>38</b>
<b>B.7 Instrument/Equipment Calibration and Frequency .....</b>	<b>39</b>
B.7.a Calibration and Frequency of Calibration .....	39
B.7.b Calibration Methodology .....	39
B.7.c Calibration Resolution and Documentation .....	39
<b>B.8 Inspection/Acceptance for Supplies and Consumables .....</b>	<b>40</b>
B.8.a Supplies, Consumables, and Responsibilities .....	40
<b>B.9. Indirect Data Measurements .....</b>	<b>40</b>
<b>B.9.a Pressure and Temperature Monitoring .....</b>	<b>40</b>
B.9.a.1.a Data Sources .....	40
B.9.a.2 Relevance to Project .....	40
B.9.a.3 Acceptance Criteria .....	40
B.9.a.4 Resources/Facilities Needed .....	40
B.9.a.5 Validity Limits and Operating Conditions .....	41
<b>B.9.b Induced Seismicity Monitoring .....</b>	<b>41</b>
B.9.b.1 Data Sources .....	41
B.9.b.2 Relevance to Project .....	42
B.9.b.3 Acceptance Criteria .....	43
B.9.b.4 Resources/Facilities Needed .....	43
B.9.b.5 Validity Limits and Operating Conditions .....	43
<b>B.9.c Vertical Seismic Profile .....</b>	<b>43</b>
B.9.c.1 Data Sources .....	43
B.9.c.1.a. Survey Design .....	43
B.9.c.1.b Equipment and Procedures .....	45
B.9.c.1.c Data Analysis and Reporting .....	46
B.9.c.1.d Time-Lapse Monitoring .....	47
B.9.c.1.e Time-Lapse Methodology .....	47
B.9.c.1.f 4D Survey Design .....	48
B.9.c.1.g 4D Processing .....	48
B.9.c.2 Relevance to Project .....	48
B.9.c.3 Acceptance Criteria .....	49
B.9.c.4 Resources/Facilities Needed .....	49
B.9.c.5 Validity Limits and Operating Conditions .....	50
<b>B.9.d Surface Air Monitoring .....</b>	<b>50</b>
B.9.d.1 Data Sources .....	50
B.9.d.3 Acceptance Criteria .....	50
B.9.d.4 Resources/Facilities Needed .....	50

---

B.9.d.5 Validity Limits and Operating Conditions.....	50
<b>B.9.e Ecosystem Stress Monitoring.....</b>	<b>51</b>
B.9.e.1 Data Sources.....	51
B.9.e.3 Acceptance Criteria.....	51
B.9.e.4 Resources/Facilities Needed.....	51
B.9.e.5 Validity Limits and Operating Conditions.....	51
<b>B.10 Data Management.....</b>	<b>51</b>
B.10.a Data Management Scheme .....	51
B.10.b Recordkeeping and Tracking Practices .....	51
B.10.c Data Handling Equipment/Procedures .....	51
B.10.d Responsibility .....	52
B.10.e Data Archival and Retrieval.....	52
B.10.f Hardware and Software Configurations.....	52
B,10.g Checklists and Forms .....	52
<b>C. Assessment and Oversight.....</b>	<b>52</b>
<b>C.1 Assessments and Response Actions.....</b>	<b>52</b>
C.1.a Activities to be Conducted .....	52
C.1.b Responsibility for Conducting Assessments.....	53
C.1.c Assessment Reporting.....	53
C.1.d Corrective Action.....	53
<b>C.2 Reports to Management .....</b>	<b>53</b>
C.2.a QA Status Reports .....	53
<b>D. Data Validation and Usability.....</b>	<b>54</b>
<b>D.1 Data Review, Verification, and Validation.....</b>	<b>54</b>
D.1.a Criteria for Accepting, Rejecting, or Qualifying Data.....	54
<b>D.2 Verification and Validation Methods.....</b>	<b>54</b>
D.2.a Data Verification and Validation Processes.....	54
D.2.b Data Verification and Validation Responsibility .....	54
D.2.c Issue Resolution Process and Responsibility.....	54
D.2.d Checklist, Forms, and Calculations .....	54
<b>D.3 Reconciliation with User Requirements.....</b>	<b>55</b>
D.3.a Evaluation of Data Uncertainty.....	55
D.3.b Data Limitations Reporting .....	55

## List of Figures

[illegible]

## List of Tables

[illegible]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

## Title and Approval Sheet

This Quality Assurance and Surveillance Plan is approved for use and implementation at the River Parish Sequestration Project, operated by River Parish Sequestration, LLC. The signatures below denote the approval of this document and intent to abide by the procedures outlined within it.

---

Signature

---

Date

---

Printed Name

---

Title

---

Signature

---

Date

---

Printed Name

---

Title

---

Signature

---

Date

---

Printed Name

---

Title

---



## **Distribution List**

The following project participants will receive the completed Quality Assurance and Surveillance Plan and all future updates for the duration of the project.

### **Contact**

Title

Address

City, State, Zip

E: email

T: phone

### **Contact**

Title

Address

City, State, Zip

E: email

T: phone

## List of Acronyms/Abbreviations

AoR	Area of Review
CO <sub>2</sub>	carbon dioxide
DAS	distributed acoustic sensing
DTS	distributed temperature sensing
EPA	Environmental Protection Agency
FID	flame ionization detector
FLIR	forward-looking infrared
GC	gas chromatography
ft	feet
hZ	hertz
LELAP	Louisiana Environmental Laboratory Accreditation Program
mg/L	milligram(s) per liter
MIT	mechanical integrity test
MVA	monitoring, verification, and accounting
NDIR	non-dispersive infrared
PNC	pulse neutron capture
ppb	parts per billion
ppm	part per million
psi	pound(s) per square inch
QA/QC	quality assurance/quality control
QASP	<i>Quality Assurance and Surveillance Plan</i>
RPS	River Parish Sequestration
RPSP	River Parish Sequestration Project
SOP	Standard Operating Procedure(s)
TCD	thermal conductivity detector
TDS	total dissolved solids
UIC	underground injection control
µg/L	microgram(s) per liter
USDW	underground source of drinking water
VSP	vertical seismic profile

## **A. Project Management**

### **A.1 Project/Task Organization**

#### A.1.a Key Individuals and Responsibilities

River Parish Sequestration, LLC, (RPS) will lead the project testing and monitoring activities with participation from several subcontractors. [REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

#### A.1.b Independence from Project Quality Assurance Manager and Data Gathering

Third parties independent and outside of the project management structure will analyze, process, or witness physical samples collected and other data gathered as part of the monitoring, verification, and accounting (MVA) program. RPS will provide a final list of vendors, subcontractors, and independent testing labs with access to the monitoring data generated through this project prior to requesting authorization to commence injection.

#### A.1.c QA Project Plan Responsibility

RPS will be responsible for maintaining and distributing the official, approved *Quality Assurance and Surveillance Plan* (QASP). RPS will periodically review this QASP and consult with the United States Environmental Protection Agency (EPA) and Louisiana Department of Natural Resources (LDNR) as changes are warranted.

[REDACTED]

[REDACTED]

[REDACTED]

## **A.2 Problem Definition/Background**

### A.2.a Reasoning

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

#### A.2.b Reasons for Initiating the Project

[REDACTED]

[REDACTED]

[REDACTED] The project is located in one of the most concentrated clusters of existing industrial emissions (CO<sub>2</sub> per square mile) in America. [REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

#### A.2.c Regulatory Information, Applicable Criteria, Action Limits


According to the Class VI rule, owners or operators of Class VI wells are responsible for assuring the following throughout a project's duration: that the injection well maintains its mechanical integrity; that USDWs are not at risk; and that fluid migration and the extent of pressure elevation are compliant with the limits outlined in the permit application. Monitoring throughout the project includes mechanical integrity tests (MITs), groundwater quality monitoring, injection well testing during operation, and tracking of the CO<sub>2</sub> plume and the associated pressure front. This QASP describes both the measurements that will be recorded as well as the accompanying procedures that will be followed to ensure the quality of the data is such that it can be confidently used to make decisions throughout the project.


### **A.3 Project/Task Description.**

[REDACTED]


[REDACTED]


[REDACTED]























\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_


[illegible]





























[Redacted text line]

[Redacted text line]

[Redacted text line]

[Redacted text line]

[Redacted text line]

[Redacted text line]



[REDACTED]

#### A.5.b Training Provider and Responsibility

All personnel training will be provided by the operator or by the subcontractor responsible for the data collection activity.

#### **A.6 Documentation and Records**

Each monitoring focus area produces distinct types of data and has distinct data-management needs (input, storage, processing, manipulation, querying, access/output). [REDACTED]

[REDACTED]

[REDACTED]

#### A.6.a Report Format and Package Information

RPS will provide a semi-annual report for EPA and LDNR containing all required project data as specified by the UIC Class VI permit. Data will be provided in electronic or other formats as required by the UIC Program Director and Office of Conservation Commissioner.

#### A.6.b Other Project Documents, Records, and Electronic Files

Other documents, records, and electronic files will be provided as required by the UIC Program Director and Office of Conservation Commissioner, and may include laboratory QC test results or well logs.

#### A.6.c Data Storage and Duration

RPS or a designated contractor will maintain the required project data as described in the records plan.

#### A.6.d QASP Distribution Responsibility

A representative from RPS will be designated as the responsible party for ensuring that all those on the distribution list will receive and maintain the latest copy of the approved QASP.

### **B. Direct Data Generation and Acquisition**

#### **B.1 Sampling Process Design**

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

#### B.1.a Design Strategy

The overall strategy and approach for testing and monitoring is given in depth in the *Testing and Monitoring Plan*.

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

---

<sup>2</sup> Resource Conservation and Recovery Act. 42 U.S.C. 6901 et seq. (1976).

<sup>3</sup> Comprehensive Environmental Response, Compensation, and Liability Act. 42 U.S.C. 9601 et seq. (1980).

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

---

[REDACTED]

[REDACTED]


[REDACTED]


[REDACTED]


[REDACTED]


[REDACTED]


















































































## Figures


- 100












RPS Project

July 2023

**Figure**  
**B.9.c-1**






RPS Project

July 2023

**Figure**  
**B.9.c-2**



RPS Project

July 2023

**Figure**  
**B.9.c-3**